



SERVICE BULLETIN INDEX

SB-1	Issue-1	Revised seat harness attachment points
SB-2	Issue-1	Clevis pins with split pins
SB-3	Issue-1	Drain holes in elevator
SB-4	Issue-1	Pitot static tube security
SB-5	Issue-1	Revised fuel filter
SB-6	Issue-1	Exposed terminals
SB-7	Issue-1	Relay supports (sharp corners)
SB-8	Issue-1	Rose joints binding
SB-9	Issue-1	Jury strut clearance
SB-10	Issue-1	Short bolts in critical areas
SB-11	Issue-1	Vapour return system
SB-12	Issue-1	Hinge bolt security
SB-13	Issue-1	Rudder return springs
SB-14	Issue-1	Incorrect screws in critical areas
SB-15	Issue-1	Electrical fuel check valve bypass
SB-16	Issue-1	Elevator horn cracking – factory built
SB-17	Issue-3	Elevator horn cracking – kit built
SB-18	Issue-1	Stub axle cracking
SB-19	Issue-1	Exhaust inspection around cockpit heater jacket
SB-20	Issue-1	Cockpit carbon monoxide detector
SB-21	Issue-1	Seat support tube rotation
SB-22	Issue-1	Incorrect length bolts fitted to cockpit tubes
SB-23	Issue-1	Incorrect length bolts fitted to stub axle
SB-24	Issue-1	Bolts in rudder horn fouling on rear composite
SB-25	Issue-1	Crack in weld on wing root rib

SB-26	Issue-1	Wing leading edge spar
SB27	Issue-1	Engine mount crack